Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
S1	600455	(stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:32
S2	106714	((stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:32
S3	24796	S1 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 electrode)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:37
S4	247	S3 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:41
S5	4820	S2 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 electrode)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:37
S6	11	S5 and (diamond near4 carbon)	US-PGPŲ B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:41
S7	6158	S3 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:41
S8	1046	S5 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:41
S 9	118	S7 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:44
S10	2	S8 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:42
S 11	0	S9 and 73/76\$4.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:42

S12	65	S9 and (electric\$4 near2 field)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 10:23
S13	36	S12 and ((chang\$4 alternat\$4) near4 conduct\$6)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/07 16:45

Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L8	2257	("DLC" near2 film) (hard near2 carbon near3 coat\$4)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:51
L9	541	8 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 (conductor electrode))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:52
L10	219	8 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 (conductor electrode)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:52
Lll	225	9 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:52
L12	219	10	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:52
L13	93	10 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:52
L14	33	11 and (stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:53
L15	. 0	13 and ((stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:53
L16	9	13 and ((stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 11:53
L17	9	8 near4 (shift\$4 move mov\$5 deform\$4 deflect\$4)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 12:43

L18	5	("5466431" "5352493" "5718976" "6080470"	US-PGPU B; USPAT;	OR	OFF	2005/06/08 12:43
		"5797623").pn.	ЕРО; ЈРО			

Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L19	108	73/762.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 12:59
L20	0	19 and (("DLC" near2 film) (hard near2 carbon near3 coat\$4))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08
L21	0	19 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 13:00
L22	1173	73/762-769.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 12:59
L23	0	22 and (("DLC" near2 film) (hard near2 carbon near3 coat\$4))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 13:00
L24	2	22 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/08 13:00